Work Ord Thursday, May											Page 1	
Item ID: D206-642-347 Revision ID:				4	Accept					Setup Star Sto		
Item Name: Start Date: Required Date Reference:	Wearshoe 5/27/2010 : 6/4/2010 Return 2010	Start Qty: 2.00 Req'd Qty: 2.00 / RA110029				Cust Item II Customer:	D:				·	
Approvals:	Process Plan: QC:		Date:	10527	Tooling: _ SPC (Y/N):		Date:		F	Run Star Stoj		
Sequence ID/ Work Center I	D	Operation Description			Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr								·		
QC Quality Control		1x B573 1x B525	batches are: 04 @ CHG002 32 @ CHG002 e found comple		0.00	-178			€V			
*110 Packaging Packaging	8	Memo New par stock.			0.00 Re 0.00 the new batch # @ CHO	G002, to return to	4	\$ C	10-	b -1 - 60/0	5/	2
120 QC		QC21- Final Inspecti	on - Work Ordo	er Release	0.00					_/c	106/0	, M

Quality Control

10-6-01

Work Order ID 59177 Page 1 Thursday, May 27, 2010 D206-642-347 Item ID: **Revision ID:** Item Name: Wearshoe Draw Nbr: Start Qty: 2.00 **Start Date:** 5/27/2010 **Revision Nbr:** Required Date: 6/4/2010 Reqd Qty: 2.00 Return 2010 / RA110029 Reference: **Cust Item ID: Customer ID: Description:** Sales Order: Process Plan: _____ Date: ____ Tooling: Approvals: Date: Date: _____ SPC (Y/N): QC: Date:

Hours

Run

Set Up



Accept

Qty

Reject

Qty

Reject

Number

Insp.

Stamp

Tool # Plan

Code

Tool ID

Sequence Work Center Operation

Description

ID

ID